

Facility Summary in DAWSON County in the City of GLENDIVE

Location: EAST END CONOCO GLENDIVE
 11801 MARILL AVE
 GLENDIVE, MT 59330 DAWSON
Contact: Ron Serpe, (800) 540-8325

Sys Fac ID: 11-00033
Last Inspected On: 1/4/2012
Operating Permit Renewal Date: 7/21/2018

Owners/Operators: Gregory Cross, Owner (406)-252-5519 CROSS PETROLEUM SERVICE INC
 PO BOX 1078
 BILLINGS MT 59103-1078

Gregory Cross, UST Class A Operator
 Timothy Fife, UST Class A Operator
 RJ Serpe, UST Class A Operator
 RJ Serpe, UST Class B Global Operator
 Ron Serpe, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	01	2/9/2015	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff, High Level Alarm
5535		2/5/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		3/20/2015	TS-550 EVO , Incon	Continuous Interstitial Monitor, Not Listed	Yes
9	01	2/9/2015	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff, High Level Alarm
5536		2/5/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		3/20/2015	TS-550 EVO , Incon	Continuous Interstitial Monitor, Not Listed	Yes
10	01	2/9/2015	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff, High Level Alarm
5537		2/5/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000		3/20/2015	TS-550 EVO , Incon	Continuous Interstitial Monitor, Not Listed	Yes

Facility Summary in DAWSON County in the City of GLENDIVE

Location: EAST END CONOCO GLENDIVE
 I1801 MARILL AVE
 GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-00033
Last Inspected On: 1/4/2012
Operating Permit Renewal Date: 7/21/2018

Contact: Ron Serpe, (800) 540-8325

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
11	01	2/9/2015	Fiberglass Reinforced Plastic	Flexible Plastic	Positive Shutoff, High Level Alarm
5538		2/5/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
4,000		3/20/2015	TS-550 EVO , Incon	Continuous Interstitial Monitor, Not Listed	Yes

Facility Summary in DAWSON County in the City of GLENDIVE

Location: DAWSON COMMUNITY AIRPORT
402 DRY CREEK RD
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-02455

Last Inspected On: 6/15/2015

Operating Permit Renewal Date: 9/29/2018

Contact: Craig . Hostetler, (406) 687-3372

Owners/Operators: Dawson County, Owner

(406)-687-3372 ATTN: AIRPORT MANAGER
207 W BELL ST
GLENDIVE MT 59330-1616

Leon Baker, Operator

(406)-687-3372 318 S TAYLOR AVE
GLENDIVE MT 59330-2440

Leon Baker, UST Class A Operator

Craig Hostetler, UST Class A Operator

Leon Baker, UST Class B Operator

Craig Hostetler, UST Class B Operator

Leon Baker, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	21	11/21/1994	Cathodically Protected Steel	Other	Positive Shutoff
824		7/29/2012	None	Secondary Containment Chase	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Galvanic
Aviation Gas		9/5/2013	Automatic Tank Gauging 0.2	Continuous Interstitial Monitor	
8,000		8/25/2011	EECO 1500 , EMCO Electronics		
5	42	1/1/1974	Unknown	Steel	
825	Yes		None	none	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Not Applicable, Galvanic
Jet Fuel		9/5/2013	Deferred	MLLD Line Tightness Testing	
200		1/23/2015			

Facility Summary in DAWSON County in the City of GLENDIVE

Location: BERGS TIRE INC
2111 W TOWNE ST
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-03214

Last Inspected On: 4/11/2013

Operating Permit Renewal Date: 7/20/2016

Contact: Jay Berg, (406) 377-5286

Owners/Operators: Berg Tire, Owner (406)-377-5286 2111 W TOWNE ST
GLENDIVE MT 59330-3214
James Berg, UST Class A Operator
James Berg, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	28	3/26/1987	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
601			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current, Galvanic
Gasoline		4/11/2013	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		1/23/2013			
2	28	3/26/1987	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
600			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current, Galvanic
Diesel		4/11/2013	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
6,000		1/23/2013			
3	28	3/26/1987	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
599			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current, Galvanic
Gasoline		4/11/2013	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		1/23/2013			

Facility Summary in DAWSON County in the City of GLENDIVE

Location: BERGS TIRE INC
2111 W TOWNE ST
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-03214
Last Inspected On: 4/11/2013
Operating Permit Renewal Date: 7/20/2016

Contact: Jay Berg, (406) 377-5286

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	28	3/26/1987	Cathodically Protected Steel	Steel	Flapper Valve (Auto Shutoff)
598			Impressed Current	None	Yes
Currently in Use			Mechanical Line Leak Detector	Pressurized	Impressed Current, Galvanic
Diesel		4/11/2013	Automatic Tank Gauging 0.2	MLLD Line Tightness Testing	
12,000		1/23/2013			

Facility Summary in DAWSON County in the City of GLENDIVE

Location: T & E WHISTLE STOP INC
1320 N MERRILL AVE
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-04213

Last Inspected On: 3/18/2013

Operating Permit Renewal Date: 6/9/2016

Contact: Tim Mort, (406) 365-2177

Owners/Operators: T & E Whistle Stop Inc, Owner (406)-365-2177 PO BOX 1313
GLENDIVE MT 59330-1313

Lynn Becker, UST Class A Operator
Timothy Mort, UST Class A Operator
Lynn Becker, UST Class B Operator
Evelyn Mort, UST Class B Operator
Timothy Mort, UST Class B Operator
Victoria Shoopman, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	31	5/6/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
4308			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		3/15/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	
10,000		9/8/2012			
2	31	5/6/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
4309			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		3/15/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	
10,000		10/14/2011			
3	31	5/6/1984	Bare Steel	Steel	Flapper Valve (Auto Shutoff)
4310			Impressed Current	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		3/15/2013	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2	
10,000		9/12/2012			

Facility Summary in DAWSON County in the City of GLENDIVE

Location: MINI MART 710 1105093
 322 E BARRY ST
 GLENDIVE, MT 59330 DAWSON
Contact: (406) 365-6111

Sys Fac ID: 11-05093
Last Inspected On: 9/5/2013
Operating Permit Renewal Date: 1/15/2017

Owners/Operators: Mini Mart Inc Pueblo, Owner (719)-948-3071 442 KEELER PKWY
 PUEBLO CO 81001-4813

Randal Liebnow, UST Class A Operator
 John Sumowski, UST Class A Operator
 Shirley Treece, UST Class A Operator
 Derrick Trimble, UST Class A Operator
 Wanda Koffler, UST Class B Operator
 Richie Lesser, UST Class B Operator
 Timothy Osterman, UST Class B Operator
 Stevie Ulstad, UST Class B Operator
 CARL WATKINS, UST Class B Operator
 Randal Liebnow, UST Class B Global Operator
 Anthony Mosmiller, UST Class B Global Operator
 Toni Mullen, UST Class B Global Operator
 Hiede Richardson, UST Class B Global Operator
 Derrick Trimble, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	19	9/1/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
1636			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel		11/22/2011	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000					

Facility Summary in DAWSON County in the City of GLENDIVE

Location: MINI MART 710 1105093
 322 E BARRY ST
 GLENDIVE, MT 59330 DAWSON
Contact: (406) 365-6111

Sys Fac ID: 11-05093
Last Inspected On: 9/5/2013
Operating Permit Renewal Date: 1/15/2017

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	19	9/1/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
1637			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline		11/22/2011	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000					
6	19	9/1/1996	Fiberglass Reinforced Plastic	Flexible Plastic	Flapper Valve (Auto Shutoff)
1638			None	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasohol/Ethanol		11/22/2011	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	
10,000					

Facility Summary in DAWSON County in the City of GLENDIVE

Location: TRAIL STAR CAR AND TRUCK STOP
EXIT 213 MT HIGHWAY 16
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-05754

Last Inspected On: 5/14/2015

Operating Permit Renewal Date: 9/29/2018

Contact: Brad Dickhaut, (406) 365-0557

Owners/Operators: Trail Star LLC, Owner (406)-377-2322 DBA TRAIL STAR CAR AND TRUCK STOP
PO BOX 557
GLENDIVE MT 59330-0557

CHERYL HAGGERY, UST Class A Operator

CHERYL HAGGERY, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	17	11/30/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4274			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
4,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
6	17	11/30/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4275			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
7	17	11/30/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4276			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
12,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: TRAIL STAR CAR AND TRUCK STOP
EXIT 213 MT HIGHWAY 16
GLENDIVE, MT 59330 DAWSON
Contact: Brad Dickhaut, (406) 365-0557

Sys Fac ID: 11-05754
Last Inspected On: 5/14/2015
Operating Permit Renewal Date: 9/29/2018

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	17	11/30/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4277			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
8,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
9	17	11/30/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4278			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	Automatic Tank Gauging 0.2	
15,000			TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: QWEST GLENDIVE CENTRAL OFFICE
119 W VALENTINE ST
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-06870

Last Inspected On: 11/11/2015

Operating Permit Renewal Date: 11/16/2018

Contact: Kevin Robison, (801) 237-3006

Owners/Operators: Qwest Corporation, Owner	(801)-237-3006	250 E 200 S #1601 SALT LAKE CITY UT 84111
Qwest Corporation, Operator	(801)-237-3006	250 E 200 S #1601 SALT LAKE CITY UT 84111
Thomas J Pitts, UST Class A Operator		
Kevin Robison, UST Class A Operator		
Thomas J Pitts, UST Class B Operator		
Dennis A Franks, UST Class B Global Operator		
Thomas J Pitts, UST Class B Global Operator		
Kevin Robison, UST Class B Global Operator		

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	22	4/1/1993	Fiberglass Reinforced Plastic	Fiberglass Reinforced Plastic	High Level Alarm
1726			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Automatic Tank Gauging 0.2, Continuous Interstitial Monitor	MLLD Line Tightness Testing	
553		11/11/2015	TLS-300 , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: JOYS GLENDIVE SERVICE INC
74 HIGHWAY 16
GLENDIVE, MT 59330 DAWSON
Contact: Bill Clemens, (608) 575-8642

Sys Fac ID: 11-07770
Last Inspected On: 11/6/2014
Operating Permit Renewal Date:

Owners/Operators: William Clemens, Owner (608)-575-8642 PO BOX 457
WAUNAKEE WI 53597
Glenn Lawres, UST Class A Operator
Glenn Lawres, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
6	17	5/28/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1511			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline		6/14/2013	Not Listed	Continuous Interstitial Monitor	
8,000					
7	17	5/28/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1512			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Gasoline		6/14/2013	Not Listed	Continuous Interstitial Monitor	
4,000					
8	17	5/28/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1513			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		6/14/2013	Not Listed	Continuous Interstitial Monitor	
6,000					
9	17	5/28/1998	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1514			Double-Walled	Double-Walled	Yes
Temporarily Out of Use			Mechanical Line Leak Detector	Pressurized	Not Applicable
Diesel		6/14/2013	Not Listed	Continuous Interstitial Monitor	
2,000					

Facility Summary in DAWSON County in the City of GLENDIVE

Location: HOLIDAY STATIONSTORE 271
701 N MERRILL AVE
GLENDIVE, MT 59330 DAWSON
Contact: Bruce Anthony, (406) 365-2221

Sys Fac ID: 11-08061
Last Inspected On: 2/2/2016
Operating Permit Renewal Date: 7/12/2019

Owners/Operators: Rocky Mountain Oil Co Inc, Owner (952)-830-8899 ATTN: ENVIRONMENTAL DIRECTOR
PO BOX 1224
MINNEAPOLIS MN 55437-1123

Stephen Reckinger, UST Class A Operator
Dean Townsend, UST Class A Operator
Ronald VanDenBroeke, UST Class A Operator
Jeremiah French, UST Class B Operator
Greg Brewer, UST Class B Global Operator
Stephen Reckinger, UST Class B Global Operator
Travis Struckman, UST Class B Global Operator
Dean Townsend, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	36	10/1/1979	Bare Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3002			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	Yes
12,000		9/25/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	36	10/1/1979	Bare Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3003			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	Yes
8,000		9/25/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
3	36	10/1/1979	Bare Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3004			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000		9/25/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: HOLIDAY STATIONSTORE 271
701 N MERRILL AVE
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-08061

Last Inspected On: 2/2/2016

Operating Permit Renewal Date: 7/12/2019

Contact: Bruce Anthony, (406) 365-2221

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	36	10/1/1979	Bare Steel	Fiberglass Reinforced Plastic	Ball Float Valve
3001			Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	Yes
12,000		9/25/2009	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: West Park Cenex
2200 W TOWNE ST
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-08908

Last Inspected On: 7/6/2015

Operating Permit Renewal Date: 10/9/2018

Contact: Charli Green, (406) 365-6282

Owners/Operators: Cross Petroleum Services Glendive, Owner (406)-377-8325 PO BOX 1388
GLENDIVE MT 59330-1388
Gregory Cross, UST Class A Operator
RJ Serpe, UST Class A Operator
RJ Serpe, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	16	9/1/1999	Unknown	Fiberglass Reinforced Plastic	High Level Alarm
553	Yes		None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		3/11/2015	TLS-350/Gilbarco EMC , Veeder Root		
5	16	9/1/1999	Unknown	Fiberglass Reinforced Plastic	High Level Alarm
554	Yes		None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Gasoline			Deferred	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
12,000		2/5/2015	TLS-350/Gilbarco EMC , Veeder Root		
6	16	9/1/1999	Unknown	Fiberglass Reinforced Plastic	High Level Alarm
555	Yes		None	None	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Not Applicable
Diesel			Deferred	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000		2/7/2015	TLS-350/Gilbarco EMC , Veeder Root		

Facility Summary in DAWSON County in the City of GLENDIVE

Location: WESTGATE CENEX
56 HIGHWAY 16
GLENDIVE, MT 59330 DAWSON
Contact: James Steffan, (406) 365-8325

Sys Fac ID: 11-08909
Last Inspected On: 7/7/2015
Operating Permit Renewal Date: 10/31/2018

Owners/Operators: Cross Petroleum Services Glendive, Owner/Operator (406)-377-8325 PO BOX 1388
GLENDIVE MT 59330-1388
Gregory Cross, UST Class A Operator
Timothy Fife, UST Class A Operator
RJ Serpe, UST Class A Operator
RJ Serpe, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	54	5/22/1961	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm, Ball Float Valve
556		7/13/2012	Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000		7/6/2012	Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	
2	54	5/22/1961	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
557		7/13/2012	Lined Interior/Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Diesel		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
8,000		8/9/2011	Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	
5	24	2/7/1992	Cathodically Protected Steel	Fiberglass Reinforced Plastic	High Level Alarm
558		7/13/2012	Impressed Current	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Impressed Current
Gasoline		7/7/2015	Automatic Tank Gauging 0.2	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000		7/4/2012	Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: GLENDIVE COMBUSTION TURBINE
 366 FAS 355
 GLENDIVE, MT 59330 DAWSON
Contact: Gary Flakker, (406) 365-2551

Sys Fac ID: 11-09400
Last Inspected On: 8/4/2015
Operating Permit Renewal Date: 11/17/2018

Owners/Operators: Montana Dakota Utilities Co, Owner (800)-472-2150 400 N 4TH ST
 BISMARCK ND 58501-4022

Kalle Kuether, UST Class A Operator
 Jim Shields, UST Class A Operator
 Chad Miller, UST Class B Operator
 Terry Ringen, UST Class B Operator
 Jody Gustafson, UST Class B Global Operator
 Jim Shields, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	28	7/1/1987	Cathodically Protected Steel	Steel	
1692	Yes	10/4/2012	None	Double-Walled	Yes
Currently in Use			Auto Dialer	Pressurized	Not Applicable
Diesel			Deferred	Continuous Interstitial Monitor	
75,000			ILS-350 , Veeder Root	Manual Interstitial Monitor	

Facility Summary in DAWSON County in the City of GLENDIVE

Location: BN GLENDIVE FUELING FACILITY
310 N MERRILL AVE
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-09528

Last Inspected On: 11/20/2013

Operating Permit Renewal Date: 12/4/2016

Contact: (406) 265-0483

Owners/Operators: Michael J Perrodin, Owner (406)-265-0483 BURLINGTON NORTHERN RAILROAD
235 MAIN ST
HAVRE MT 59501-3523

Brett Bailey, UST Class A Operator
Tim Christianson, UST Class A Operator
Lloyd Roberts, UST Class A Operator
Leslie Metzger, UST Class B Operator
Loren Music, UST Class B Operator
Randall Sorkness, UST Class B Operator
Robin Utgaard, UST Class B Operator
Richard Wegmann, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
4	24	9/1/1991	Bare Steel	Steel	
505	Yes		None	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Gravity Feed	Galvanic, Impressed Current
Diesel		10/22/2013	Deferred	Continuous Interstitial Monitor	
680,000					
12	26	12/28/1989	Cathodically Protected Steel	Fiberglass Reinforced Plastic	
504			Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	Gravity Feed	Galvanic, Impressed Current
Mixture		10/2/2013	Continuous Interstitial Monitor	Continuous Interstitial Monitor	
16,000					

Facility Summary in DAWSON County in the City of GLENDIVE

Location: GLENDIVE MEDICAL CENTER
202 PROSPECT DR
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 11-09735

Last Inspected On: 8/19/2014

Operating Permit Renewal Date: 12/19/2017

Contact: Larry Perkins, (406) 345-3306

Owners/Operators: Glendive Medical Center, Owner (406)-345-3306 202 PROSPECT DR
GLENDIVE MT 59330-1999
Sam Durham, UST Class A Operator
Mike Ryan, UST Class A Operator
Craig Torno, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	20	11/16/1995	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
1223		8/28/2012	Double-Walled	Double-Walled	Yes
Currently in Use			Continuous Interstitial Monitoring	U.S. Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Continuous Interstitial Monitor	
4,010			TLS-300 , Veeder Root		

Facility Summary in DAWSON County in the City of GLENDIVE

Location: CROSSROADS CONOCO GLENDIVE
58 HIGHWAY 16
GLENDIVE, MT 59330 DAWSON

Sys Fac ID: 56-13872

Last Inspected On: 12/29/2014

Operating Permit Renewal Date: 3/14/2018

Contact: Jim Steffon, (406) 365-2728

Owners/Operators: Gregory Cross, Owner (406)-252-5519 CROSS PETROLEUM SERVICE INC
PO BOX 1078
BILLINGS MT 59103-1078

Gregory Cross, UST Class A Operator
Timothy Fife, UST Class A Operator
RJ Serpe, UST Class A Operator
RJ Serpe, UST Class B Global Operator
Ron Serpe, UST Class B Global Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
1	16	6/26/1999	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4043			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Diesel			Automatic Tank Gauging 0.1, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, Approved Remote Monitoring	
10,000		3/8/2012	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	
2	16	6/26/1999	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4044			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline			Automatic Tank Gauging 0.1, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
15,000		3/8/2012	Gilbarco EMC Basic , Gilbarco	Continuous Interstitial Monitor	
3	16	6/26/1999	Steel Clad	Flexible Plastic	Flapper Valve (Auto Shutoff)
4045			Double-Walled	Double-Walled	Yes
Currently in Use			Electronic Line Leak Detector	Pressurized	Galvanic
Gasoline			Automatic Tank Gauging 0.1, Continuous Interstitial Monitor	Automatic Tank Gauging 0.1, Automatic Tank Gauging 0.2, ELLD Line Tightness Testing	
10,000		3/8/2012	TLS-350/Gilbarco EMC , Veeder Root	Continuous Interstitial Monitor	

Facility Summary in DAWSON County in the City of RICHEY

Location: FARMERS ELEVATOR/RICHEY
111 RAILROAD AVE
RICHEY, MT 59259 DAWSON

Sys Fac ID: 11-05898
Last Inspected On: 8/31/2015
Operating Permit Renewal Date: 2/2/2019

Contact: David Corbin, (406) 951-0997

Owners/Operators: CHS Inc - Richey, Owner/Operator (406)-773-5758 PO BOX 37
RICHEY MT 59259

David Corbin, UST Class A Operator
David Corbin, UST Class B Operator
Jana Olson, UST Class B Operator
Lance Schipman, UST Class B Operator

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
5	14	7/11/2001	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4314			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline		10/29/2012	Manual Interstitial Monitor	Deferred	
4,000					
6	14	7/11/2001	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4315			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Gasoline		10/29/2012	Manual Interstitial Monitor	Deferred	
4,000					
7	14	7/11/2001	Steel Clad	Fiberglass Reinforced Plastic	Flapper Valve (Auto Shutoff)
4316			Double-Walled	None	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel		10/29/2012	Continuous Interstitial Monitor, Manual Interstitial Monitor	Deferred	
4,000					

Facility Summary in DAWSON County in the City of RICHEY

Location: FARMERS ELEVATOR/RICHEY
111 RAILROAD AVE
RICHEY, MT 59259 DAWSON

Sys Fac ID: 11-05898

Last Inspected On: 8/31/2015

Operating Permit Renewal Date: 2/2/2019

Contact: David Corbin, (406) 951-0997

Tank Id	Age	Installed	Tank Material of Construction	Piping Material	Overfill Types
Tag Number	AST	Sump Tightness	Secondary Option	Secondary Option	Spill Protected
Status		Inventory Control	Catastrophic L.D. Type 3.0	Piping Type	CP Met Types
Product		Tank/Pipe CP	Tank Detection	Primary Pipe Detection	Vapor Recovery
Capacity		Line Tightness	ATG Type	Secondary Pipe Detection	Energy Act
8	00	4/1/2015	Fiberglass Reinforced Plastic	Flexible Plastic	High Level Alarm, Positive Shutoff
5572		5/4/2015	Double-Walled	Double-Walled	Yes
Currently in Use			Not Required	Safe Suction	Not Applicable
Diesel			Continuous Interstitial Monitor	Deferred	
8,000			Other , Other	Not Listed	